

~~SECRET~~  
~~CONFIDENTIAL~~  
Office Memorandum

UNITED STATES GOVERNMENT

TO : Chief, Engineering Division, OC

10th SPM 8-857  
DATE: 17 November 1958

FROM : Chief, Supplemental Programs Staff, OC

SUBJECT: CB-4 Playback Unit 

ILLEGIB

1. Attached is a list of the damages observed after uncrating the CB-4 Playback Equipment received from   
 The photographs included are referenced in the attached list. The equipment was received on 12 November 1958 and uncrated immediately.

25X1  
25X1

2. No attempt was made to place the equipment into operation as the AC power cord had been severed, therefore no estimate of electrical damage has been made.

3. It is requested that appropriate action be taken to repair the damages as soon as possible in order to permit evaluation of the CB-3 Recorder.

25X1

Distribution:  
Orig & 2 - Addressee

Attachment  
List of damages

|            |    |          |         |               |       |
|------------|----|----------|---------|---------------|-------|
| DOC        | 45 | REV DATE | 23/4/80 | BY            | 37169 |
| ORIG COMP  | 33 | CPI      | 56      | TYPE          | 2     |
| ORIG CLASS | 5  | PAGES    | 2       | REV CLASS     | C     |
| JUST       | 22 | NEXT REV | 2010    | AUTH: HR 10-2 |       |

~~SECRET~~~~CONFIDENTIAL~~

~~SECRET~~

CONFIDENTIAL

LIST OF DAMAGES  
TO  
CB-4 PLAYBACK UNIT

## FRONT END:

1. RECORDER

- a. Two front push levers broken. (Ref. Fig. #1 (a))
- b. Front panel lightly bent. (Ref. Fig. #1 (b))
- c. One (possibly more) screw missing from recorder deck. (Ref. Fig. #1 (c))

2. 1000 cps SIGNAL COMPARATOR

- d. Two front panel screws missing and one screw about to break. (Ref. Fig. #1 (d))

3. FREQUENCY CHANGER UNIT

- e. Front filler panel badly bent. (Ref. Fig. #2 (e))
- f. One front panel screw missing and one screw loose. (Ref. Fig. #1 (f))
- g. Voltage adjustment control broken. (Ref. Fig. #1 (g))
- h. Frequency range hi-lo control missing (possible this control knob was removed by contractor). (Ref. Fig. #1 (h))
- i. Frequency control knob bent out of true. (Ref. #2 (i))

## REAR END VIEW:

1. RECORDER

- j. Flywheel assembly completely loose from unit. (Fig. 4 (j))
- k. Amplifier unit on the bottom of the recorder deck hanging by a few wires. Other wires broken loose. (Fig. #3 (k))

2. FREQUENCY CHANGER UNIT

- l. Unit broken loose from rack (Fig. #3 (l))
- m. Screws and Brack sheared off. (Fig. #3 (m))

3. MISCELLANEOUS

- n. Ten various screws and bolts found loose when the unit was unpacked. (Fig. #4 (n))
- o. "Supermolly Pole" piece has one knob broken off and the other two knob shafts bent. (Fig. #4 (o))

~~SECRET~~ CONFIDENTIAL